

**From:** "Michael Hansen" <Mhansen@rbgengineering.com>  
**To:** <dshaver@andalex.com>, <jlewis@andalex.com>, <jsorensen@andalex.com>, <James\_Kohler@blm.gov>, <Jeff\_McKenzie@blm.gov>, <Stan\_Perkes@blm.gov>, <Steve\_Falk@blm.gov>, <steve\_rigby@blm.gov>, <ecc@emerytelcom.net>, <mkstilson@hotmail.com>, "Brad Price" <bprice@rbgengineering.com>, <bret Dixon@utah.gov>, <davemarble@utah.gov>, <karlhouskeeper@utah.gov>, <pamgrubaughlittig@utah.gov>, <petehess@utah.gov>, <waynehedberg@utah.gov>  
**Date:** 1/12/2006 12:32:00 PM  
**Subject:** Grassy Trail Dam- Monitoring December 2005

During December both seismic accelerometers were up and running after being re-calibrated and moved in November 2005. The unit (BE96090) which was originally on the dam was move to a new location on the hillside, while the unit (BE9689) from the hillside in now located on the dam. During the month of December, 8 natural/MIS events were recorded on the hillside and 1 event on the dam. The highest MIS acceleration recorded was on the hillside, with an acceleration of 0.0232g. Within the general area 2 earthquakes were reported by the University of Utah Seismograph Stations (UUSS) with magnitudes of 1.0 and 1.7. Neither of these events were recorded by our instruments.

Slope movement inclinometers were read on 12/30/05. These inclinometers do not show detectable movement from the baseline readings taken on 12/9/05.

Piezometer readings taken on 12/30/05 are consistent with the baseline readings taken on 12/9/05. The included chart shows readings taken since 8/30/05. It should be noted from the chart that the old observation well "OB-1" continues to show somewhat erratic movement, just as it has in the past. Erratic movement on this well is not a concern.

The PDF attachments below includes charts and tables showing piezometer, inclinometer and accelerometer readings take on 12/30/05.

Michael Hansen  
Engineering Geologist

RB&G ENGINEERING Inc.  
1435 West 820 North  
Provo Ut. 84601


Ph 801-374-5771  
SLC 801-521-5771  
Fax 801-374-5773

email mhansen@rbgengineering.com

Grassy Trail Dam, Carbon County, Utah  
\* New Locations, Hillside unit #9690 Dam #9689


Event Report: Event LList - c:\blastevent\grassy~1.05\1230~1.05



Type	Serial No.	Date/Time	Tran Peak (mm/s)	Vert Peak (mm/s)	Long Peak (mm/s)	PVS1 (mm/s)	Trigger	Tran Accel (g)	Vert Accel (g)	Long Accel (g)	Description	Post Event Note first line
LOG	BE9689	Dec 6 /05 16:21:07	***	***	***	***	***	***	***	***	Start Monitoring	Start Monitoring
LOG	BE9690	Dec 6 /05 17:08:43	***	***	***	***	***	***	***	***	Start Monitoring	Start Monitoring
W	BE9690	Dec 6 /05 17:09:05	0.159	1.17	0.619	1.31	Vert	0.0166	0.101	0.0497	Instantel Inc.	man made
LOG	BE9690	Dec 6 /05 17:10:03	***	***	***	***	***	***	***	***	Keyboard Stop	No events recorded. (Keyboard Exit)
LOG	BE9690	Dec 6 /05 17:10:21	***	***	***	***	***	***	***	***	Start Monitoring	Start Monitoring
W	BE9689	Dec 9 /05 16:43:39	0.651	0.968	0.508	1.15	Tran	0.119	0.0895	0.0597	Instantel Inc.	man made
W	BE9690	Dec 11 /05 15:55:36	0.937	0.365	0.365	0.951	Tran	0.0116	0.00829	0.00663	Instantel Inc.	man made
W	BE9690	Dec 11 /05 18:51:53	0.873	0.460	0.349	0.887	Tran	0.0116	0.00663	0.00663	Instantel Inc.	
W	BE9690	Dec 16 /05 12:00:56	0.651	0.317	0.270	0.655	Tran	0.00829	0.00663	0.00663	Instantel Inc.	
W	BE9690	Dec 20 /05 02:27:03	0.730	0.413	0.397	0.761	Tran	0.00829	0.00663	0.00663	Instantel Inc.	
W	BE9690	Dec 20 /05 12:05:03	0.714	0.317	0.286	0.715	Tran	0.00829	0.00663	0.00663	Instantel Inc.	
W	BE9690	Dec 21 /05 09:16:51	1.13	0.714	0.540	1.13	Tran	0.0133	0.00829	0.00829	Instantel Inc.	
W	BE9690	Dec 21 /05 17:56:48	0.714	0.365	0.333	0.764	Tran	0.00829	0.00663	0.00663	Instantel Inc.	
W	BE9690	Dec 23 /05 10:59:41	1.03	0.603	0.540	1.05	Tran	0.00994	0.00829	0.00663	Instantel Inc.	
W	BE9690	Dec 29 /05 17:52:37	2.44	0.825	1.21	2.49	Vert	0.0232	0.00994	0.00829	Instantel Inc.	Event has highest PGA recorded for Dec at 0.0232g
LOG	BE9690	Dec 29 /05 17:52:44	***	***	***	***	***	***	***	***	Stop Monitoring	Event recorded. (Keyboard Exit)
W	BE9689	Dec 29 /05 17:52:45	1.56	1.19	0.635	1.60	Vert	0.0116	0.00994	0.00829		
W	BE9689	Dec 30 /05 11:49:45	0.476	0.889	0.238	0.903	Vert	0.0613	0.143	0.0414		Man made
LOG	BE9689	Dec 30 /05 11:52:02	***	***	***	***	***	***	***	***	Keyboard Stop	No events recorded. (Keyboard Exit)
LOG	BE9690	Dec 30 /05 14:09:39	***	***	***	***	***	***	***	***	Start Monitoring	Event recorded. (Keyboard Exit)
W	BE9690	Dec 30 /05 14:09:39	1.73	***	2.43	***	Vert	0.141	3.30	0.199	Instantel Inc.	Man made
LOG	BE9690	Dec 30 /05 14:09:52	***	***	***	***	***	***	***	***	Stop Monitoring	Event recorded. (Keyboard Exit)






EVENTS RECORDED per MONTH			
	Hillside unit	Dam unit	UUSS Earthquakes
Jan	6	na	0
Feb	31	na	4
March	60	1	1
April	86	10	5
May	125	10	2
June	72	4	5
July	31	2	2
Aug	72	28	30
Sept	72	42	36
Oct	11	2	4
Nov	*	1	8
Dec	8	1	2


\* Instruments being moved and recalibrated






























**RB&G  
ENGINEERING  
INC.**  
Provo, Utah

Figure    Reservoir Elevation and Piezometer Readings  
            August 30, 2004 to December 30, 2005  
Grassy Trail Dam and Reservoir

[illegible]